• • • • • • • • • • • • • • • • • • • •	Zone) RE	PORT NO.
TOPIC Alt Loennewitz Air 1A	field	; Эмпектронотронотронотронотронот негонал артали градительнух жереней расстанство в жереней станство по выстанство в вы
X EVALUATION	PLACE OBTAINED_	RETUING
DATE OF CONTEN	Surreus sicilian sel im a trous activamente timbraminamente material activity retrieva l'encident	Leana
DATE OBTAINED.	DATE PREPARED_	13 February 1951
REFERENCES		
PAGESENCLOS	URES (NO. & TYPE)	
REMARKS		
andromental and a reconstruction of the section of	- Language de contra de co	Makaya daribi sangala hadi sang Midana, mama kinamin Barkana, Samana Sanganayan Barkan menon ang pagaman ang ma
Applications and Australia (PALA) - MACO 1874, NOON (STANGERS TORS, 1987) - 1 (PASY) Admirator, 1984 (N. 167) American		

SOURCE

1. Between 7 and 10:30 a.m. on 23 January 1951, the Alt Loennewitz N 52/E 8h) airfield was observed from its southern and eastern edges. The visibility was approximately 1,500 meters but decreased to 200 meters later. Eight jet aircraft with swept-back wings were parked on the eastern end of the runway. They had antennae sloping to the rear, fitted behind their cockpits, which were covered with tarpaulins. The

25X1A

- 2. Five single-engine, low-wing monoplanes with radial engines and two-seater cockpits were parked on the runway. ** Aircraft engines were being warmed up between 7:20 and 8 a.m. The runway lights were not switched on. Thite ground signals were seen in the middle of the landing field at 8 a.m. Shortly afterwards, approximately 100 men were heard singing. Early in the morning, approximately 60 men and six to eight tank trucks and radio trucks were seen near the single-engine, low-wing monoplanes. At 10 a.m. the engines of those planes were started and they taxied to the hangars. The men marched behind the aircraft.
- 3. The radio must which was braced and two or three small temporary buildings were still in the eastern extension of the runway. ****

 The radio must had an overhead line leading to a wooden but which was dug into the ground approximately 50 meters from the eastern end of the runway. The lights along the southern edge of the runway were still there. Two or three small guardhouses, which were interconnected by overhead lines, were located along the southern edge of the landing field.

25X1C

LĢ

CLASSIFICATION

No Change in Class.

Declassified

Class. Changed To: TS

Auth.: PR 70-2

By: OLF